

## DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC


INSPECTION DATE: 6/3/15				
WEATHER: 59°F, Overcast				
INSPECTED BY: D. West, K. Homza				

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	0943 hrs. Standing vale in road ruts and
Erosion	N	N	along perimeter of pend new road. No Standing water
Low Point, B dike*			
Flow	N	N	0946 hrs. No standing water. Sand buys and
Erosion	N	N	rip rap in place.
Outfall		E Commence	
water surface El.			0950 hrs. Standing water behind sundbays and corner conrects weir. Slight drip at weir near to NW corner 56".
(top of stoplogs to water)			564.

\* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): Rainfall event of 1.33" ending 6/2/15 around 1400 hrs. Standing water at the base of the slope between A + B.

HT 0753 LT 1437



behird Sandbays